

Release Notes 2.00.05

elmeg IP120

1. BugFixes:

- Gerät lehnt INVITE in besonderen Fällen ab
- Roboter-Stimme mit der neuesten Software-Version behoben
- DHCP-Fehler: BAD_ADDRESS
- Das Gerät erkennt die neuen DNS-Werte erst nach einem Neustart
- Kein Zeilenumbruch bei SIP-Nachrichten
- Bei einem eingehenden Anruf mit automatischer Amtsholung wird kein interner Name angezeigt
- Umlaute (ÄÖÜ) werden nicht richtig angezeigt
- Fehlende Übersetzung

2. Bekannte Probleme:

- FUN-28 Gesprächsverlust für 1-2 Sekunden bei Gesprächsbeginn
- FUN-34 „One way speech“ beim Weiterleiten (bei unterschiedlichen Apparaten)
- FUN-32 Nur spezielle DTMF-Nummern werden erkannt
- FUN-25 Wechsel der Lautstärke von Anruf zu Anruf
- FUN-23 Manchmal frieren die Telefone während eines Anrufs ein

3. Update:

Automatisches Update: über die Telefonanlage (Release 2.00.00 < 2.00.05)

Laden Sie die Systemsoftware-Dateien aus dem Download-Bereich www.bintec-elmeg.com auf Ihre Telefonanlage. Nach dem Update auf Release 2.00.05 wird ein Factory Reset empfohlen.

Die Tasten und die SIP-Registrierung werden von der Telefonanlage autoprovioniert.

Manuelles Update: Wenden Sie sich bitte an das Support-Center der bintec elmeg GmbH, um die entsprechenden Dateien zu erhalten. Laden Sie die Systemsoftware auf Ihr **elmeg IP120**-Telefon.

1. BugFixes:

- Device rejects INVITE in special cases
- Robot voice with latest software versions
- DHCP failure: BAD_ADDRESS
- Device does not recognize new DNS values without rebooting device
- No line break on SIP messages
- No internal name is shown via a incoming call to device with automatic outside line
- Umlauts (ÄÖÜ) are not displayed correctly
- Missing translation

2. Known issues:

- FUN-28 Talk loss at beginning of conversation for 1-2 seconds
- FUN-34 „One way speech“ while forwarding (at different devices)
- FUN-32 Only special DTMF numbers will be recognized
- FUN-25 Changing volume from call to call
- FUN-23 Sometimes Phone freezing during call

3. Update:

Automatic Update: via the PBX (Release 2.00.00 < 2.00.05)

Load the system software files from the download section www.bintec-elmeg.com to you PBX. After updating to Release 2:00:05 a factory reset is recommended.

The keys and the SIP registration are auto provisioned of the PBX system.

Manual Update: Please contact the bintec elmeg customer service to obtain the relevant files. Please load the system software to you **elmeg IP120** phone.